

## APPLICATION

### TSW-4

## Acryli-Master™ Anti-Graffiti Coating

**IMPORTANT: All applicators must register with Technical Support 800-447-2334 to review application procedures before beginning application.**

### SURFACE PREPARATION

#### **Concrete/Stucco**

Remove any loose stucco, efflorescence, or laitance. If painting is desired use only 100% exterior acrylic paint. Allow new stucco or concrete to cure at least 30 days before coating.

#### **Siding**

Clean the surface thoroughly by scrubbing with warm, soapy water. Rinse thoroughly.

#### **Wood, Composition Board**

Patch all holes and imperfections. Prime as directed. Paint with 100% exterior acrylic paint.

### APPLICATION

**APPLICATION:** Apply with airless sprayer when feasible to avoid foaming problems. If applied too heavily TSW-4 Acryli-Master will run, sag, and become semi-opaque. Do not apply in direct sunlight or when surfaces are hot to the touch. Catch runs and sags immediately with pad painter or dry brush before product begins to cure and harden. Always work to a wet edge. Four (4) coats recommended. When airless spraying is not practical Acryli-Master may be applied with brush and/or roller. See Product Data Sheet for more information.

#### **Brush/Roller/Pad**

Use a nylon brush, paint pad, or appropriate nap roller with synthetic cover. NOTE - Airless spraying is strongly advised. TSW-4 Acryli-Master will foam profusely when rolled. When airless spraying is not practical

TSW-4 Acryli-Master may be applied with brush and/or roller. When rolling or brushing thin 5% with water and immediately work surface with dry brush or pad painter to eliminate any bubbles that form.

#### **Spray-Airless**

Pressure 1500 - 2000 psi  
Tip .015"-.0191  
Reduction: On natural surfaces thin first coat with 40% water. On painted surfaces product may be thinned with 5% water for best spray pattern.

Protect adjacent surfaces.

#### **Spray-Conventional**

Not recommended

### CLEANUP INFORMATION

Clean spills and spatters immediately with soap and water. Clean hands and tools immediately after use with soap and water. After cleaning, flush Spray equipment with TSW-5 Spray Clean or mineral spirits or suitable preservative to prevent rusting of the equipment. Follow manufacturers safety recommendations when using mineral spirits.

### LABEL ANALYSIS

Solids by Weight (Approximate)  
26%

#### **Drying Time**

@77F, 50% RH  
Touch 1 Hour  
Recoat 1 Hour

#### **Cautions**

Do not apply at temperatures below 50F or greater than 90F. Protect from freezing. Non-photo chemically reactive.

Contains Ethylene glycol butyl ether. Use only with adequate ventilation. To avoid overexposure, open windows and doors or use other means to ensure fresh air. If you experience eye watering,

headaches, or dizziness, increase fresh air, or wear respiratory protection (NIOSH/MSHA TC23C or equivalent) or leave the area. Follow respirator manufacturer's directions for respirator use. Avoid contact with eyes and skin. Wash hands after using. Keep container closed when not in use.

For further safety information consult Material Safety Data Sheet.

**FIRST AID:** In case of eye contact, flush thoroughly with large amounts of water. Get medical attention if irritation persists. If swallowed, get medical attention immediately.

### **HELPLINE/HOTLINE**

Applicators must register with our technical department at 800-447-2334 to review specific application information before beginning the product application.

**Failure to properly register within 14 days of application will void any warranty.**

DO NOT TAKE INTERNALLY.  
KEEP OUT OF THE REACH OF CHILDREN.



This Stuff Works, Inc.  
2021 Las Positas Ct #147  
Livermore, CA 94551  
800-447-2334 / 800-4graffiti  
[www.graffitimaster.com](http://www.graffitimaster.com)